



---

BY TEXTRON AVIATION

# 510 Communiqué

**Communiqué #MC 510-006  
Serial Number - 0001 and On  
May 2021**

## **ATA 71 – PWC SB**

Textron Aviation (TA) would like to highlight for operators that PWC has released Service Bulletin (SB) 63112 that affects some PW615 engines. The SB recommends the inspection and replacement of affected accessory gear box (AGB) breather seals. Failure of the seal may lead to oil leaks and increased consumption. Please reference SB 63112 to see if either of your engines serials may be affected.

PWC also has Commercial Support Program Notification (CSPN) 1009157 to provide assistance to those complying with SB 63112. This CSPN expires January 19<sup>th</sup>, 2022.

If you have additional questions or need further support, please contact your Field Service Representative or the Textron Aviation Team Powerplants Technical Support line at, 316.517.6232, or [teampowerplants@txtav.com](mailto:teampowerplants@txtav.com).