

## REVISION TRANSMITTAL

This sheet transmits Revision 1 to SB525-34-100, which:

- A. Adds that SB525-34-107 *Navigation - Garmin Hardware and Software Update to Version 4.8.9* must be performed prior to or in conjunction with this service bulletin to the NOTE in the EFFECTIVITY section.
- B. Adds Step 4 to make sure the FANS 1/A option is installed.

**NOTE:** This revision replaces the original issue of SB525-34-100 in its entirety.

### REVISION COMPLIANCE

NO EFFECT. Airplanes previously modified are not affected by this revision.

### LOG OF REVISIONS

Original Issue	March 26, 2021
Revision 1	August 25, 2021



**TITLE**

NAVIGATION - FUTURE AIR NAVIGATION SYSTEM (FANS) 1/A INSTALLATION

**EFFECTIVITY****MODEL**

525 (Citation M2)

**SERIAL NUMBERS**-0800 and On, airplanes equipped with ACARS  
and a Datalink Radio (GDR 66)

**NOTE:** Airplanes -0800 thru -1047 must perform SB525-34-97 *Navigation - Garmin Software Update To Version 4.8.11* or SB525-34-107 *Navigation - Garmin Hardware and Software Update to Version 4.8.9* prior to or in conjunction with this service bulletin.

**NOTE:** Airplanes -1048 and On are equipped with next generation hardware from the factory and will be eligible to install this service bulletin.

**NOTE:** Airplanes that are not equipped with a Datalink Radio (GDR 66) must incorporate SB525-23-25 prior to or in conjunction with this service bulletin.

**NOTE:** Airplanes that are not equipped with ACARS must incorporate SB525-23-22 prior to or in conjunction with this service bulletin.

**NOTE:** Textron Aviation-owned or Textron Aviation-authorized Service Centers are the only facilities that can complete this service document.

**REASON**

To install the FANS option on the airplane.

**DESCRIPTION**

This service document provides parts and instructions to install the FANS option.

**COMPLIANCE**

OPTIONAL. This service document can be accomplished at the discretion of the owner.

A service document published by Textron Aviation may be recorded as *completed* in an aircraft log only when the following requirements are satisfied:

- 1) The mechanic must complete all of the instructions in the service document, including the intent therein.
- 2) The mechanic must correctly use and install all applicable parts supplied with the service document kit. Only with written authorization from Textron Aviation can substitute parts or rebuilt parts be used to replace new parts.
- 3) The mechanic or airplane owner must use the technical data in the service document only as approved and published.
- 4) The mechanic or airplane owner must apply the information in the service document only to aircraft serial numbers identified in the *Effectivity* section of the document.
- 5) The mechanic or airplane owner must use maintenance practices that are identified as acceptable standard practices in the aviation industry and governmental regulations.

Original Issue - March 26, 2021  
Revision 1 - August 25, 2021SB525-34-100  
Page 1 of 3

Textron Aviation Customer Service, P.O. Box 7706, Wichita, KS 67277, U.S.A. 1-316-517-5800

This document contains technical data and is subject to U.S. export regulations. This information has been exported from the United States in accordance with export administration regulations. Diversion contrary to U.S. law is prohibited. ECCN: 9E991

No individual or corporate organization other than Textron Aviation is authorized to make or apply any changes to a Textron Aviation-issued service document or flight manual supplement without prior written consent from Textron Aviation.

Textron Aviation is not responsible for the quality of maintenance performed to comply with this document, unless the maintenance is accomplished at a Textron Aviation-owned Service Center.

#### APPROVAL

Textron Aviation received FAA approval for the technical data in this publication that changes the airplane type design.

#### FLIGHT CREW OPERATIONS

No Changes

#### CONSUMABLE MATERIAL

No specialized consumable materials are required to complete this service document.

#### TOOLING

No specialized tooling is required to complete this service document.

#### WEIGHT AND BALANCE INFORMATION

Negligible

#### REFERENCES

Cessna Model 525 (0685 and 0800 and On) Maintenance Manual

#### PUBLICATIONS AFFECTED

Cessna Model 525 (0685 and 0800 and On) Maintenance Manual

#### ACCOMPLISHMENT INSTRUCTIONS

1. The 010-00330-J5 ACARS FANS 1/A Enablement Card must be available before the software is installed.
2. Connect external electrical power to the airplane.

**NOTE:** The G3000 avionics system may lock up if external electrical power is removed during software loading. Connecting the battery is suggested to reduce the risk of locking up the G3000 avionics system if external power is interrupted.

3. Do the Airplane Options Installation procedures. (Refer to the Model 525 (-0685 and -0800 and On) Maintenance Manual, Chapter 34, Garmin G3000 Integrated Avionics System - Adjustment/Test (Airplanes with Software Version 4.8 or later).)
4. Make sure that the FANS 1/A is installed.
  - A. Select the Home screen on either GTC.
  - B. Make sure that there is an ATC Datalink icon in the lower left corner of the GTC screen.
  - C. Select ATC Datalink.
  - D. Make sure that there is an ADS-C tab on the left side of the GTC screen.
5. Remove external electrical power from the airplane.

6. Make an entry in the airplane logbook that states compliance and method of compliance with this service document.

**NOTE:** Textron Aviation recommends that compliance with all service documents is reported to a maintenance tracking system provider.

- Complete a record of compliance. (Maintenance Transaction Report, Log Book Entry, or other record of compliance.)
- Put a copy of the completed record of compliance in the airplane logbook.
- Send a copy of the completed record of compliance to the maintenance tracking system provider used.

### MATERIAL INFORMATION

Order the kit/parts below to install this modification.

NEW P/N	QUAN- TITY	KEY WORD	OLD P/N	INSTRUCTIONS/ DISPOSITION
010-00330-J5	1	FANS 1/A Enablement Card	None	

\* Please contact your Regional Textron Aviation Parts Distribution Customer Support Team for current cost and availability of parts listed in this service document. Phone at 1-800-835-4000 (Domestic) or 1-316-517-5603 (International).

For more information, please visit the TAPD Support & Aftermarket Account Management website at <https://ww2.txtav.com/Parts/Promos/TAPD>.

Based on availability and lead times, parts may require advanced scheduling.



**TITLE**

NAVIGATION - FUTURE AIR NAVIGATION SYSTEM (FANS) 1/A INSTALLATION

**TO:**

Cessna Citation M2 Owner

**REASON**

To install the FANS option on the airplane.

**COMPLIANCE**

OPTIONAL. This service document can be accomplished at the discretion of the owner.

**LABOR HOURS**

For planning purposes only:

**WORK PHASE**

Modification

**LABOR-HOURS**

As Required

**MATERIAL AVAILABILITY****PART NUMBER**

010-00330-J5

**AVAILABILITY**

\*

**COST**

\*

\* Please contact your Regional Textron Aviation Parts Distribution Customer Support Team for current cost and availability of parts listed in this service document. Phone at 1-800-835-4000 (Domestic) or 1-316-517-5603 (International).

For more information, please visit the TAPD Support & Aftermarket Account Management website at <https://ww2.txtav.com/Parts/Promos/TAPD>.

Based on availability and lead times, parts may require advanced scheduling.

**WARRANTY**

None

**NOTE:** As a convenience, service documents are now available online to all our customers through a simple, free-of-charge registration process. If you would like to sign up, please visit the Customer Access link at [www.txtavsupport.com](http://www.txtavsupport.com) to register.

