

---

# Revision Transmittal

December 11, 2018

## REVISION TRANSMITTAL

TO: Cessna Distributors, Single Engine Service Facilities, and CPC's

SUBJECT: Single Engine Service Bulletin SB10-27-01 Revision 1: Elevator Trim Stops Relocation

Cancels the service bulletin and is superseded by SEB-27-04 - Elevator Trim Stop Block Relocation.

**NOTE:** SEB-27-04 has updated instructions to relocate the elevator trim stop blocks.

**NOTE:** Airplanes that have previously completed SB10-27-01 - Elevator Trim Stops Relocation, it is advisable to complete SEB-27-04 because the stop block orientation and placement dimensions are updated.

## REQUIRED ACTION

Please replace any copy of SB10-27-02 with this revision sheet.

\* \* \* \* \*

