

Beechcraft



Hawker

TEXTRON AVIATION

525B Communiqué

**Communiqué #MC 525B-008
Serial Number – 0610 and On
November 2020**

ATA 34 – Garmin 4.8 Software and LRU Update

Beginning at serial 525B-0610 and On, the Garmin G3000 system has been updated to version 4.8. This update includes hardware, software, and wiring changes. The 525B Aircraft Maintenance Manual was revised in April 2020 to include maintenance instructions for this new Garmin software version. The Wire Diagram Manual (revision A0) has also been revised, but the current Illustrated Parts Catalog (revision 21) has not yet been updated with the new LRU part numbers. Until it is revised, please refer to ICA-525B-34-00003 Garmin 4.8 Software and LRU Update ICA Supplement, which was released in January 2020. The part numbers for the new components are listed in Appendix A of this ICA supplement. Software loader card part numbers are also included.

ICA-525B-34-00003 does not give authorization to modify prior aircraft serials to upgrade to the Garmin 4.8 software, it only provides instructions for continued airworthiness of the system. A separate service bulletin is in development that will allow Garmin 4.8 software to be installed on prior serial number CJ3+ aircraft.

It is very important to note that until the 525B Illustrated Parts Catalog is revised, the only document with the new hardware part numbers is ICA-525B-34-00003. This ICA supplement can be found on TxtavSupport.com by searching the “Service Documents” quick link on the home page. Select “Cessna” in the dropdown menu, “525B - CJ3+” under Model, and make sure the “ICA” blue checkbox at the bottom is highlighted, then hit “Search”. ICA Supplements are listed by model and ATA chapter. Please reference MC 525B-007 for an ICA Supplement explanation and more detailed instructions on how to search for them.

If you have additional questions or need further support, please contact your Field Service Representative or the Textron Aviation 525 Technical Support team at 1.855.832.9831, 1.316.517.7785, or team525@txtav.com.

Garmin 4.8 Software and LRU Update

ICA Supplement

MODEL NO: 525B

SUPPLEMENT NO: ICA-525B-34-00003

SUPPLEMENT DATE: 1/03/2020